# SETUP: Where to put Jumpers when wiring WatchMonPlus

1. Based on your battery setup and WatchMonPlus add jumpers to pluggable connectors as per below table (table located on back of WatchMonPlus)

## WatchMonPlus WM7

|  | JP1 | JP2 | JP3 | JP4 |
|---|---|---|---|---|
| 10C | ● |  |  |  |
| 9C | ● | ● |  |  |
| 8C | ● | ● | ● |  |
| 7C | ● | ● | ● | ● |
| 6C | ● | ● | ● | ● |
|  | JC1 | JC2 | JC3 | JC4 |

**Note that the back of the device shows the pins that each jumper relates to.**

# WatchMonPlus WM5 / MultiMon MM8

|       | JP1 | JP2 | JP3 | JP4 | JP5 |
|-------|-----|-----|-----|-----|-----|
| 14C   | ●   |     |     |     |     |
| 13C   | ●   | ●   |     |     |     |
| 12C   | ●   | ●   | ●   |     |     |
| 11C   | ●   | ●   | ●   | ●   |     |
| 10C   | ●   | ●   | ●   | ●   | ●   |
|       | JC1 | JC2 | JC3 | JC4 | JC5 |

**Note that the back of the device shows the pins that each jumper relates to.**



2.  Once Pass achieved on TestMon move the pluggable connectors to your WatchMonPlus (most negative LOW first)